

AD-A036 519

BELL HELICOPTER TEXTRON FORT WORTH TEX  
FLIGHT TEST EVALUATION OF OH-58A TAILBOOM FAILURE DURING AUTORO--ETC(U)  
MAR 73 T L SANDERS

F/G 1/3

DAAJ01-70-C-0057


UNCLASSIFIED


206-194-134

USAAVSCOM-TR-77-14

NL

| OF |  
AD  
A036519





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

—  
ADA036519


USAAVSCOM  
REPORT - TR 77-14

12  
B.S.

# FLIGHT TEST EVALUATION OF OH-58A TAILBOOM FAILURE DURING AUTOROTATION LANDINGS

Thomas L. Sanders  
BELL HELICOPTER COMPANY  
Post Office Box 482  
Fort Worth Texas 76101

14 March 1973  
Final Report



APPROVED FOR PUBLIC RELEASE  
DISTRIBUTION UNLIMITED

Prepared for  
U.S. ARMY AVIATION SYSTEMS COMMAND  
Maintenance Engineering Division  
Post Office Box 209  
St. Louis, MO 63166

054200

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 18 USAAVSCOM TR-77-14	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) 6 FLIGHT TEST EVALUATION OF OH58A TAILBOOM FAILURE DURING AUTOROTATION LANDINGS.		5. TYPE OF REPORT & PERIOD COVERED 9 Final rept.
7. AUTHOR(s) 10 THOMAS L. SANDERS		6. PERFORMING ORG. REPORT NUMBER 14 206-194-134
9. PERFORMING ORGANIZATION NAME AND ADDRESS Bell Helicopter Company P.O. Box 486 Ft. Worth, TX 76101		8. CONTRACT OR GRANT NUMBER(s) 15 DAAJ01-70-C-0057(22)
11. CONTROLLING OFFICE NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS DA Form 3149R Data Item 05-005
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Commander US Army Bell Plant Activity P.O. Box 1605 Ft. Worth, TX 76101		12. REPORT DATE 11 14 Mar 1973
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited		13. NUMBER OF PAGES 59 12 610.
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
18. SUPPLEMENTARY NOTES This report presents the results of Product Improvement Task 69-45. See USAAVSCOM TR 77-10 for additional information.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Flight test, Ground tiedown evaluation, Instrumentation, Test Helicopter, Ground run results, Flight Results, Tailboom Failure Evaluation, Reduced Collective Evaluation, (USAASTA) Test Results.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) A flight program was initiated in September 1971 to investigate the causes of the model OH-58A tailboom failures occurring in service and to explore methods of eliminating this type of failure. From the results of this test it is concluded that the tailboom failures would not have occurred had proper autorotative techniques been observed.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

054200

13





# BELL HELICOPTER COMPANY

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101 A **Textron** COMPANY

## TECHNICAL DATA

MODEL OH-58A

No. of Pages 59 Size "A"

REPORT No. 206-194-134

DATE 3-14-73

### TITLE

FLIGHT TEST EVALUATION OF OH-58A  
TAILBOOM FAILURE DURING AUTOROTATION  
LANDINGS

PREPARED UNDER CONTRACT DAAJ01-70-C-0057(2E)

PROPRIETARY RIGHTS NOTICE IS ON PAGE ii.

BY <u>Thomas L. Sanders</u>	DATE <u>3-14-73</u>
Senior Flight Test Engineer	
CHECKED <u>W. E. Gentry</u>	DATE <u>3-14-73</u>
Chief Flight Test Engineer	
GROUP ENGR. <u>W. E. Gentry</u>	DATE <u>3-14-73</u>
Chief Flight Test Engineer	
PROJECT ENGR. <u>C. H. Hensley</u>	DATE <u>5-3-73</u>
CHIEF of LABS * <u>—</u>	DATE <u>—</u>
D. E. R. * <u>—</u>	DATE <u>—</u>
<u>—</u>	DATE <u>—</u>
<u>—</u>	DATE <u>—</u>

\* WHEN APPLICABLE

PROPRIETARY RIGHTS NOTICE

This data is furnished with unlimited data rights  
to the U. S. Government in accordance with the  
provisions of Contract No. DAAJ01-70-C-0057.

ACCESSION FOR	
NTIS	White Section <input checked="" type="checkbox"/>
DOC	Bull Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION.....	
BY.....	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and or SPECIAL
A	

# LIST OF FIGURES

<u>Figure</u>		<u>Page</u>
1-10	Collective Stick Position Versus Main Rotor Speed During Run-On Auto Landing	11-20
11	Time History of Normal Autorotation Landing	21
12	Time History of Autorotation Landing with Tailboom Failure	22
13	Runway Contact During Autorotation Landing with Tailboom Failure	23
14-20	BHC Photographs of Tailboom Failure	24-27
21-22	Pylon Position During Tailboom Failure	28-29
23	Collective Cable Restraint as Installed on the Model OH-58A, S/N 41155	30
24	Collective Stick Position Versus Main Rotor Blade Angle	31
25-30	Time Histories of Autorotation Landings Obtained with FAA Runk Grid Camera	32-37
31	Time History of Autorotation Landing by USAASTA Test Team	38
32-34	Height-Velocity Time History Plots	39-41
35	Runway Gradient at Arlington Airport	42

LIST OF TABLES

<u>Table</u>		<u>Page</u>
I	Instrumentation Set-Up Sheets	43
II	Log of Flights	47
III	Oscillograph Parameters	49
IV	Height-Velocity and Runway Gradient Grid Camera Data	50



FLIGHT TEST EVALUATION OF OH-58A  
TAILBOOM FAILURE DURING AUTOROTATION  
LANDINGS

SUMMARY

A flight test program was initiated in September 1971, under Contract No. DAAJ01-70-C-0057(2E) and Product Improvement Task No. 69-45, to investigate the cause(s) of the Model OH-58A tailboom failures occurring in service and to explore methods of eliminating this type of failure.

A three phase company investigation was initiated and consisted of (1) a mathematical analysis and associated computer runs, (2) a series of ground vibration tests, and (3) a ground tiedown and flight test. The results of the flight evaluation, phase 3, are presented in this report.

Two Model OH-58A Helicopters, S/N's 41080 and 41155, were utilized during the evaluation.

With a telemetry capability of monitoring critical parameters, a series of tests were conducted and data obtained. Analysis of the data that were recorded during autorotations showed that when touchdowns were made at abnormally high speeds and at abnormally low rotor rpm, aft fuselage wrinkling and failure of the tailboom occurred. This damage occurred when loads were introduced into the fuselage at the pylon spike stops via the main rotor flapping stops. This was demonstrated during the evaluation when a tailboom failure was duplicated to study the influential circumstances associated with the failure.

Results of this test indicate that autorotation touchdown airspeeds in excess of 30 knots should be avoided and upon ground contact the collective should be smoothly reduced as soon as touchdown conditions permit. Also, tests conducted with the collective range reduced by approximately 20 percent showed a substantial reduction in main rotor flapping and pylon behavior.

From the results of this test, it is concluded that the tailboom failures experienced by the Army (which caused initiation of this test program) would not have occurred had proper autorotative techniques been observed. That is to say that primarily cyclic control should be utilized to flare the helicopter so as to arrest forward airspeed and initial rate of descent. Application of collective thereafter should occur and only in close proximity to the ground to arrest rate of descent for the last few feet of altitude until ground contact is made. Upon ground contact, collective should be smoothly reduced as soon as practical; not increased. This technique is recognized by helicopter pilots throughout the world as the safe and proper method of making a full autorotative landing. Conversely, a technique of flying the helicopter to the ground, primarily by the use of collective, is improper in that (1) it is inherently unsafe (miscalculation by the pilot can



SUMMARY - (cont)

result in the helicopter being too high off the ground with no arresting capabilities remaining), and (2) it results in abnormally high touchdown speeds and abnormally low rotor rpm. Other types of rotor systems for other helicopters flown in this manner are equally unforgiving.

Tests were conducted at the Bell Helicopter Company (BHC) Flight Research Center, Arlington, Texas.

FLIGHT TEST EVALUATION OF OH-58A  
TAILBOOM FAILURE DURING AUTOROTATION  
LANDINGS

INTRODUCTION

A flight test program was initiated to investigate U. S. Army reported OH-58A tailboom failures during autorotation touchdown landings. The intent of the investigation was to explore methods or techniques of eliminating these failures and make appropriate recommendations.

A standard Model OH-58A Helicopter, S/N 41080, was instrumented and several hypotheses were to be investigated. Test emphasis was directed towards the following ground and possible flight evaluations.

A. Ground Run Tiedown Evaluation of

1. Baseline pylon stability.
2. Effect of first and second drive system torsional mode on pylon damping.
3. Blade chord natural frequency and feedback at high collective pitch.
4. Damping of pylon fore and aft, lateral mode.
5. Coriolis Force Excitation.

B. Possible Flight Evaluation of

1. Binding of the main rotor flapping bearings under high collective pitch and low rotor speed resulting in an unstable rigid rotor effect producing pylon whirl and pylon stop contact.
2. Rotor blade resonant amplification (chord and/or beam) which could produce large pylon motions and high control loads.
3. The effect of significant rotor out-of-balance resulting in excessive pylon response and possible contact of the pylon stops as pylon modes are transitioned.
4. Pylon whirl induced by pylon stop contact with high rotor coning, sustained and amplified by symmetric chordwise deflection of the rotor blades.
5. High main rotor one-per-rev hub forces produced by Coriolis accelerations resulting from cyclic inputs in the presence of high rotor coning.

Additional tests were conducted on the Model OH-58A Helicopter, S/N 41155, to evaluate a reduction in the available collective range.

INTRODUCTION - (cont)

Flights were performed at the BHC Flight Research Center, Arlington, Texas. The first ground run was conducted on 20 September 1971 and the last flight was completed 24 November 1971.

The dynamic characteristics of the rotor, pylon, drive train, fuselage, and skid gear were evaluated in detail by the Dynamic Group and results are on file but not presented in this report.

## INSTRUMENTATION

The airborne data acquisition system installed in the Model OH-58A Helicopter, S/N 41080, consisted of an oscillograph recorder and a telemetry package.

The oscillograph was a standard 18 channel Consolidated Electrodynamics Corporation Model S-114-P3 recorder with galvanometers. A calibrate equivalent was used to correlate the initial calibration with the data obtained.

The telemetry package consisted of BHC designed signal conditioning modules, vector voltage controlled oscillators, Model TL407, and a conic "L" band telemetry transmitter. The telemetry link had a maximum capacity of 13 data channels. The signal conditioning modules are the passive type, and insert a calibration signal at the end of each data point. The incoming telemetry multiplex signal includes a system status and reference signal which is recorded on magnetic tape in the Ground Data Center. Brush charts are used for real time display allowing data parameters to be reproduced as they occur.

### Calibrations

Standard procedures were used by the BHC Standards and Calibration Laboratory to instrument the test helicopters. Table I presents a list of calibrated items and their respective calibration numbers.

### Flight Log

A log of all ground runs and flights, listing the date, flight and/or ground run numbers, duration time and configuration, is shown in Table II.

### TEST HELICOPTER

The test helicopters used during this test program were the Model OH-58A Bell S/N's 41080 and 41155.

S/N 41080: Prior to the test flight the aircraft was leveled and the following rigging measurements were obtained.

Main Rotor Mast	5° forward, 1° left
Swashplate	
F/A Cyclic (full throw)	+17.5° forward, +8.0° aft
Lateral Cyclic (full throw)	+5.5° right, +8.0° left
Collective Pitch (full throw)	-0.5° down, +16.6° up

S/N 41155: Aircraft was received, inspected, and instrumented. The collective pitch was measured at the main rotor hub and the minimum blade angle was +0.4 degrees and the maximum blade angle was +17.7 degrees.



## RESULTS AND DISCUSSION

### Ground Run Results

The aircraft was placed on tiedown and a series of ground runs were conducted. Cyclic inputs at approximately 1.0, 2.5, and 5.0 cps were made to obtain baseline pylon stability information and to determine the effect of first and second drive system torsional mode on pylon damping. During the evaluation, main rotor thrust was varied from zero to approximately 2410 pounds.

At a main rotor speed of 200 rpm and with 91 percent collective, the maximum main rotor blade chord excitation was  $\pm 13,500$  inch-pounds. Efforts to determine the blade natural frequency were unsuccessful.

The lateral pylon stops could be contacted with a cyclic input at a main rotor rpm of 180 and 91 percent collective. Mast bumping could be induced with 100 percent collective and at a main rotor rpm of 240. Pylon contact or mast bumping did not reflect any unusual loads in the main rotor or fuselage. A maximum tailboom stress of only 4000 psi, which is a nominal load, was generated with a cyclic input of approximately 5.0 cps with a main rotor rpm of 270 and collective at 86 percent. To evaluate the Coriolis effect, cyclic inputs were made during a main rotor rpm sweep with a blade root collective of 10 degrees.

Results obtained during the ground runs did not offer any insight or peculiarities that might suggest tendencies that could result in high tailboom stresses. Also, it was very difficult to determine fuselage natural frequencies while the aircraft was secured during ground run. As a result, the decision was made to proceed to the flight evaluation.

### Flight Results

Since the tiedown results were inconclusive, investigation efforts were directed towards duplicating the tailboom failures reported by the Army. With a telemetry capability of monitoring critical parameters, a series of hovering throttle chops and touchdown autorotations were conducted. During a variety of autorotational landings, various techniques of cyclic and collective application at a disparity of main rotor rpm's were investigated. Many of the basic hypotheses became inconsequential due to the following.

1. Pylon stop contact with high main rotor coning did not indicate pylon whirl tendencies. Lateral pylon spike contact could be obtained without too much difficulty; however, no unusual loads or peculiar tendencies were evident. Fore and aft pylon spike contact was very difficult to obtain.
2. At conditions of high collective pitch and low rotor speed, there was no evidence of binding in the main rotor flapping bearing.
3. There was no evidence of rotor blade resonant amplification that could result in large pylon motions and high control loads.

## RESULTS AND DISCUSSION - (cont)

### Flight Results - (cont)

4. Cyclic inputs during conditions of high main rotor coning did not appear to influence main rotor hub forces.

A total of 36 touchdown autorotation landings and 10 throttle chops were flown to obtain data. Analysis of autorotation data began to suggest certain trends of maximum main rotor flapping with high touchdown airspeeds at low main rotor speeds of 200 rpm or less, see Figures 1 through 10. During the third flight, a tailboom failure was duplicated to study the influential circumstances associated with the failure.

### Tailboom Failure Evaluation

A review of the recorded data suggested that several factors contributed to the tailboom failure and the absence or reduction of any one factor was sufficient to prevent failure. The characteristics associated with the tailboom failure can be summarized as follows:

1. Prior to or at aircraft touchdown, the collective must be raised to the full up mechanical stop and allowed to remain at the up stop until the main rotor rpm decays to approximately 200 or less.
2. Touchdown airspeed must be sufficient to provide considerable rotor inflow.
3. Main rotor blade coning and flapping must be sufficient to produce fore and aft pylon stop contact.

The combinations of the above results in sufficient rotor-fuselage inertia to produce damaging fuselage stress loading.

Comparison of Figure 11, a time history of a normal touchdown autorotation, and Figure 12, a time history of the touchdown autorotation when the tailboom failure occurred, tend to substantiate the influence of main rotor flapping with collective position, main rotor speed, and pylon behavior associated with the failure.

Figure 13 shows aircraft ground contact and subsequent ground roll, and Figures 14 through 20 are photographs depicting test vehicle damage that occurred during the evaluation. Figures 21 and 22 depict the extent of the pylon motion during the failure.

Main rotor control and blade loads were normal during the autorotation landings and only increased after onset of the tailboom failure condition.

A vertical and roll acceleration of considerable amplitude, in excess of two g's, was observed in the cabin. At the conclusion of the landing, there was no doubt by the flight crew that damage of one form or

## RESULTS AND DISCUSSION - (cont)

### Tailboom Failure Evaluation - (cont)

another had been sustained. It is the further opinion of the flight crew that a pilot of even minimal experience would recognize that the aircraft had experienced an abnormal situation and would conduct an exterior safety of flight inspection prior to a takeoff.

Options Available for Failure Reduction: After careful review of available data, the following items were evaluated and considered as possible methods of eliminating or reducing the possibility of a failure.

1. Determine the technique the U. S. Army is using in the training of new and transition pilots, and the rationale for their techniques. Also, recommend modifications of existing techniques if deemed appropriate.
2. Provide cockpit indicator to indicate warning of excessively hard landings and potentially damaging tailboom vibrations.
3. Reduce the available collective range to avoid excessive dynamic loading and yet maintain adequate height-velocity margins.
4. Consider basic structural modifications to stiffen the critical areas, reduce stress levels, and/or produce changes in dynamic response characteristics and system coupling.
5. Provide mechanical fixes, such as pylon viscous or friction dampers, and fuselage impact and/or friction dampers.

Reduced Collective Evaluation: After reviewing the options available, indications were the best solution to the problem was that improper autorotative techniques needed revising. However, in the event the ship were landed improperly it was judged that a reduction of the collective range would be beneficial. As a result, a Model OH-58A Helicopter, S/N 41155, was instrumented and a series of tests were begun to determine the feasibility of limiting the available collective pitch during autorotation landings (Option 3). This reduction was accomplished by attaching an adjustable cable on the copilot collective stick that physically limited the maximum up position of the collective, see Figure 23. Figure 24 shows the results of a hangar calibration of collective stick position versus main rotor blade angle. A series of hovering throttle chops, slide on landings, and autorotation touchdowns at various percent of collective reduction were evaluated to determine if a reduction in the available collective would prohibit maintaining adequate height-velocity margins. During the hovering throttle chops at a gross weight (GW) of 3000 pounds, there was a definite change in the character of main rotor blade stall when the available collective blade angle was reduced to 75 percent; however, time airborne, which is an indicator of rotor capability, was also reduced. At 80 percent available collective the time airborne after throttle chop was adequate, 3.6 seconds, and pylon motion and main rotor flapping were greatly reduced.



## RESULTS AND DISCUSSION - (cont)

### Tailboom Failure Evaluation - (cont)

#### Reduced Collective Evaluation - (cont)

Six autorotation landings were accomplished with the available collective pitch reduced by approximately 20 percent, and Figures 25 through 30 present the data obtained by using the Federal Aviation Administration (FAA) Runk Grid Camera. Touchdown calibrated airspeed varied from 24 knots to 41 knots. Table III presents important oscillograph parameters recorded during the autorotation landings.

Test results indicate that the probability of tailboom failure, with the available collective range reduced by approximately 20 percent, is greatly decreased due to a reduction in main rotor flapping.

A mathematical analysis and associated computer study were conducted to evaluate the tailboom failure problem. The study was concentrated in the area of main rotor flapping versus main rotor blade angle and main rotor inflow during autorotation touchdown. Synopsis of the evaluation concluded that main rotor flapping benefits derived by the reduction of the main rotor blade angle can be reduced by an increase in rotor inflow. However, the touchdown airspeeds required to produce the mandatory rotor inflow are considered excessive and unrealistic for normal autorotation touchdowns. An autorotative touchdown in excess of 40 kts coupled with improper landing techniques is judged to be outside the reasonable and mandatory operating envelope of the helicopter. As a result, it can be concluded that the probability of a tailboom failure would be greatly reduced by improving autorotation techniques to avoid high speed touchdowns with high main rotor blade angles.

#### U. S. Army Aviation Systems Test Activity (USAASTA) Test Results

A flight evaluation of the Model OH-58A Helicopter, S/N 41155, with a reduced collective blade angle was conducted by an Army test team at the BHC Flight Research Center, Arlington, Texas, on 23 and 24 November 1971.

During the USAASTA evaluation the helicopter was first flown in the standard OH-58A configuration. The adjustable cable on the copilot collective stick was installed prior to the second flight to limit the maximum up position of the collective to 80 percent (13.6 degrees main rotor blade angle at the hub).

A series of touchdown landings were made utilizing techniques that had produced tailboom failures in the past. Figure 31 presents a time history of an autorotation touchdown landing that produced a considerably high level of vertical tailboom excitation with a near damaging stress of 17,586 psi. The pilot reported the touchdown airspeed was probably in excess of 40 knots indicated airspeed (KIAS). Visible airframe damage was limited to minor pylon upper cowling contact and

## RESULTS AND DISCUSSION - (cont)

### USAASTA Test Results - (cont)

cracked fiberglass fairing at the tailboom connection area. Aircraft damage was considered minor and tests continued. This documented autorotation landing incident is an additional substantiation of the computer study results.

The Army test team also conducted tests to determine if the present height-velocity margins could be maintained when the available collective range was reduced to avoid excessive dynamic loading. Data were obtained by using the FAA Runk Grid Camera and results are presented in Figures 32 through 34. Table IV presents the height-velocity time history data. Figure 35 shows the runway gradient at the test site. Maximum available collective was limited to 85 percent. Results of the evaluation indicated that the maximum collective utilized during the autorotation was 70 percent and as a result, shows that adequate collective is available to maintain present height-velocity margins at the altitude the test was conducted.



### CONCLUSIONS

A flight test program to investigate OH-58A tailboom failures during autorotation landings and explore methods of eliminating these failures has been completed.

The following conclusions are made on the basis of the subject flight test program.

1. The results obtained during the ground run were inconclusive.
2. Efforts to duplicate a tailboom failure were successful and as a result, many of the original hypotheses to be investigated became inconsequential.
3. The combination of maximum main rotor blade angle and flapping, low rotor rpm, rotor inflow, and pylon contact (fore and aft) has sufficient rotor-fuselage inertia to produce damaging fuselage stress loading.
4. With the available collective range reduced by approximately 20 percent, test results indicate that the probability of tailboom failure, resulting from improper autorotation techniques, is greatly reduced due to the reduction in main rotor flapping.
5. The probability of tailboom failure would be eliminated by observing proper autorotation techniques, thereby avoiding high speed touchdowns with high main rotor blade angles.

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

RELI HELICOPTER COMPANY  
POST OFFICE BOX 107 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 11  
HELI 41080 RPT 206-194-134  
FLT. 1C  
REC. 508




FIG. 1 COLL STK POSITION VS. M/R SPEED DURING RUN-ON  
AUTO LANDING.

BY  
CHECKED

BELL HELICOPTER COMPANY  
POST OFFICE BOX 187  
FORT WORTH, TEXAS

MODEL OH-58A PAGE 11  
REEL 41080 RPT 206-194-134  
FLT. 1C  
REC. 508




FIG. 1 COLL STK POSITION VS. M/R SPEED DURING RUN-ON  
AUTO LANDING.

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
PORT OFFICE, 200 400 • PORT WORTH, TEXAS

MODEL OH-58A PAGE 12  
HELI 41080 RPT 206-194-134  
FLT. 1C  
REC. 511




FIG. 2 COLL STK POSITION VS M/R SPEED DURING  
AUTO LANDING



BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

SELL HELICOPTER COMPANY  
POST OFFICE BOX 482 FORT WORTH, TEXAS

MODEL OH-58A PAGE 13  
WELL 41080 RPT 206-194-134

FLT. 1  
REC. 515




FIG. 3 COLL STK POSITION VS M/R SPEED DURING  
RUN-ON AUTO LANDING



BY  
CHECKED

BELL HELICOPTER COMPANY  
FORT WORTH, TEXAS

MODEL OH-58A PAGE 14  
HELL 41080 RPT 206-194-134  
FLT. 1C  
REC. 516




FIG. 4 COLL STK POSITION VS. M/R SPEED DURING RUN-ON  
AUTO LANDING

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
POST OFFICE BOX 407 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 15  
HELI 41080 RPT 206-194-134  
FLT. 1C  
REC. 520




FIG. 5 COLL STK POSITION VS M/R SPEED DURING RUN-ON  
AUTO LANDING

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

DELL HELICOPTER COMPANY  
POST OFFICE BOX 400 • JOLIET, ILLINOIS 61781

MODEL OH-58A PAGE 16  
HELI 41080 RPT 206-194-134  
FLT. 1D  
REC. 525




Fig. 6 COLL. STK. POSITION VS. M/R SPEED DURING RUN-ON  
AUTO LANDING

BY  
CHECKED

BELL HELICOPTER COMPANY  
POST OFFICE BOX 437 FORT WORTH, TEXAS

MODEL OH-58A PAGE 17  
HELI 41080 RPT 206-194-134

FLT. ID  
REC. 529




FIG. 7 COLL STK POSITION VS M/R SPEED DURING RUN-ON AUTO LANDING



BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
POST OFFICE BOX 482 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 18  
HELI 41080 RPT 206-194-134  
FLT. ID \_\_\_\_\_  
REC. 530




FIG. 8 COLL STK POSITION VS M/R SPEED DURING RUN-ON AUTO LANDING

BY  
CHECKED

WEST HELICOPTER COMPANY  
FILE OFFICE BOX 401 • 4001 NORTH 11TH

MODEL OH-58A PAGE 19  
WELL 41080 RPT 206-194-134

FLT. 3  
CTR. 594

SYM	OSC	STRESS LEVEL
○	≤	5000 PSI
●	≤	10000 PSI
⊖	≥	10000 PSI




FIG. 9 COLL STK POSITION VS M/R SPEED DURING  
RUN-ON AUTO LANDING

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

HELL HELICOPTER COMPANY  
7001 BELL BLVD. S.W. - SEATTLE 1, WASH.

MODEL OH-58A PAGE 20  
HELL 41080 RPT 206-194-134  
FLT. 3  
REC. 595

SYM	OSC	STRESS LEVEL
●	≤	5000 PSI
●	≤	10000 PSI
○	≥	10000 PSI






FIG. 10 COLL STK POSITION VS M/R SPEED DURING  
RUN-ON AUTO LANDING





COPY 001

PAGE 22  
RPT 206-194-134




BY \_\_\_\_\_  
 CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
 POST OFFICE BOX 482 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 23  
 RPT 206-194-134

OH58A S/N 41080  
 FLT 3

N → S



ARLINGTON AIRPORT NORTH SOUTH RUNWAY

FIG 13 RUNWAY CONTACT



Fig. 14 Model OH-58A, S/N 41080, After Tailboom Failure, BHC Photo 284188




Fig. 15 Model OH-58A, S/N 41080, Right Aft View of Tailboom Failure at Fuselage Sta. 220, BHC Photo 284185




Fig. 16 Model OH-58A, S/N 41080, Tailboom  
Failure, Left Side, Fuselage Sta.  
220, BHC Photo 284177



Fig. 17 Model OH-58A, S/N 41080, Tailboom  
Failure, Lower Surface, Fuselage  
Sta. 220, BHC Photo 284179





Fig. 18 Model OH-58A, Lower Transmission  
Case After Failure, BHC Photo 284118




Fig. 19 Model OH-58A, Pylon Area After  
Tailboom Failure, BHC Photo  
284120




Fig. 20 Model OH-58A, Transmission Cowl, Left Side, After Tailboom Failure, BHC Photo 284183

PRINTED IN U.S.A. ON CLEARPRINT TECHNICAL PAPER NO. 1015

CLEARPRINT PAPER CO. NO. C10X MILLIMETERS, 200 BY 250 DIVISIONS

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
1001 BELLEVILLE AVE. MILWAUKEE, WIS. 53213

MODEL OH-5B A PAGE 28  
BELL 41080 RPT 206-194-1  
FLT. 3  
CTR. 595

NOTE: ARROWS INDICATE TRAVEL  
WILL GO TO STOP




FIG 2/ PYLON POSITION DURING TAILBOOM FAILURE

BY  
CHECKED

BELL HELICOPTER COMPANY  
2000 DESIGNS, 4000 DESIGNS, 10000 DESIGNS

MODEL OH-58A PAGE 29  
BELL 41080 RPT 206-194-134  
FLT. 3  
CTR. 595

NOTE: ARROWS INDICATE TRAVEL  
WILL GO TO STOP




FIG: 2.2 PYLON POSITION DURING TAILBOOM FAILURE





Fig. 23 Collective Cable Restraint as  
Installed on the Model OH-58A,  
S/N 41155

BY

CHECKED

BELL HELICOPTER COMPANY

P.O. BOX 1000, HELIX, MISSISSAUGA, ONT. L4X 1L7

P.O. BOX 1000, HELIX, MISSISSAUGA, ONT. L4X 1L7

MODEL OH-58A PAGE 31

REEL 41155 RPI 206-194-134




FIG 24 COLLECTIVE STICK POSITION VS M/R BLADE ANGLE

HW 11-30-71

SHIP NO. 41153 FLT NO. 5-B  
 CTR NO. 924 ACT. GROSS WT. 2936 LB.  
 GROUND LEVEL PRESS. ALT. 650 FT.  
 GROUND LEVEL AMBIENT TEMP. 20 °C  
 $\sigma = .960$ ;  $\sqrt{g} = .980$ ; DEV. ALT. 1380 FT.  
 AVG. WIND SPEED (ALONG PATH) 11.0 FPS

FOR TAKE-OFF DISTANCE  
 OBS. TO DIST. FT. TIME TO 50 FT. HT. SEC.  
 NOMINAL ENGINE POWER SHP

FOR LANDING DISTANCE  
 TIME, 50 FEET TO GROUND CONTACT 9.62 SEC.  
 ENTRY GROUND SPEED @ 50 FT. 82.5 FT/SEC.  
 GROUND CONTACT GROUND SPEED 31.3 FT/SEC.  
 RATE OF DESCENT AT 50 FT. 26.0 FT/SEC.  
 OBSERVED AIR LANDING DIST. 477 FT.  
 OBSERVED GROUND LANDING DIST. 163 FT.  
 CALIBRATED AIRSPEED AT T.D. = 24.4 KTS.

NOTE: EVENT LIGHT NOT VISIBLE.

T.D. LOCATION FROM OBS. DATA  
 AND RUNWAY GRADIENT CORRELATION.

HORIZONTAL DISTANCE - FT. & ENGINE POWER - SHP




FIG. 25 TIME HISTORY OF LANDING RUN No. 10 ~ FLT. No. 5B

OH-58A

32  
 206-194-134

10-10-71



SHIP NO. 41150 FLT NO. 5B  
 CTR NO. 925 ACT. GROSS WT. 2926 LB.  
 GROUND LEVEL PRESS. ALT. 650 FT.  
 GROUND LEVEL AMBIENT TEMP. 20 °C  
 $\sigma = .960$ ;  $\sqrt{\sigma} = .984$ ; DEN. ALT. 1350 FT.  
 AVG. WIND SPEED (ALONG PATH) 11.0 FPS

NOTE: EVENT LIGHT NOT VISIBLE.  
 T.D. LOCATION FROM OBS. DATA  
 AND RUNWAY GRADIENT CORRELATION.

FOR TAKE-OFF DISTANCE  
 OBS. T.O. DIST. FT. TIME TO 50 FT. HT. SEC.  
 NOMINAL ENGINE POWER SHP

FOR LANDING DISTANCE  
 TIME, 50 FEET TO GROUND CONTACT 7.23 SEC.  
 ENTRY GROUND SPEED @ 50 FT. 79.0 FT/SEC.  
 GROUND CONTACT GROUND SPEED 47.5 FT/SEC.  
 RATE OF DESCENT AT 50 FT. 24.4 FT/SEC.  
 OBSERVED AIR LANDING DIST. 433 FT.  
 OBSERVED GROUND LANDING DIST. 365 FT.  
 CALIBRATED AIRSPEED AT T.D. = 33.9 KTS.





FIG 26 Time History Of Landing RUN No. 11 ~ FLT. No. 5B



04-58A

SHIP NO. 41155 FLE NO. 5-B  
 CTR NO. 926 ACT GROSS WT. 2821 LB.  
 GROUND LEVEL PRESS. ALT. 650 FT.  
 GROUND LEVEL AMBIENT TEMP. 20 °C  
 $\sigma = .960$ ;  $\sqrt{\sigma} = .980$ ; DEC. ALT. 1350 FT.  
 AVG. WIND SPEED (ALONG PATH) 11.8 FPS

NOTE: EVENT LIGHT NOT VISIBLE.  
 T.D. LOCATION FROM OBS. DATA  
 AND RUNWAY GRADIENT CORRELATION



FOR TAKE-OFF DISTANCE  
 OBS. T.D. DIST. FT. TIME TO 50 FT. HT. SEC.  
 NOMINAL ENGINE POWER SHIP  
 FOR LANDING DISTANCE  
 TIME, 50 FEET TO GROUND CONTACT SEC.  
 ENTRY GROUND SPEED @ 50 FT. 80.0 FT/SEC.  
 GROUND CONTACT GROUND SPEED 43.0 FT/SEC.  
 RATE OF DESCENT AT 50 FT. 21.9 FT/SEC.  
 OBSERVED AIR LANDING DIST. 624 FT.  
 OBSERVED GROUND LANDING DIST. 237 FT.  
 CALCULATED AIRSPEED AT T.D. = 31.9 MTS.

04-58A

34

206-194-134

FIG. 27 TIME HISTORY OF LANDING RUN NO. 12 ~ FLE. NO. 5B

J.G. 10-27-71

7872 50227

SHIP NO. 41155 FLT. NO. 5B  
 CIR. NO. 927 ACT. GROSS WT. 2941 LB.  
 GROUND LEVEL PRESS. ALT. 650 FT.  
 GROUND LEVEL AMBIENT TEMP. 80 °C  
 $\sigma = .960$ ;  $\sqrt{\sigma} = .980$ ; DEN. ALT. 1380 FT.  
 AVG. WIND SPEED (ALONG PATH) 16.0 FPS

FOR TAKE-OFF DISTANCE  
 OBS. TO. DIST. FT. TIME TO 50 FT. HT. SEC.  
 NOMINAL ENGINE POWER. SHP  
 FOR LANDING DISTANCE  
 TIME, 50 FEET TO GROUND CONTACT 10.67 SEC.  
 ENTRY GROUND SPEED 81.5 FT/SEC.  
 GROUND CONTACT SPEED 49.5 FT/SEC.  
 RATE OF DESCENT AT 50 FT. 20.0 FT/SEC.  
 OBSERVED AIR LANDING DIST. 639 FT.  
 OBSERVED GROUND LANDING DIST. 332 FT.  
 CALIBRATED AIRSPEED AT T.D. = 38.1 KTS.

NOTE: EVENT LIGHT NOT VISIBLE.

T.D. LOCATION FROM OBS. DATA  
 AND RUNWAY GRADIENT CORRELATION.

NOTE: TIME AT STOP = 23.29 SECONDS  
 HORIZ. DIST. AT STOP = 1061 FT.

HORIZONTAL DISTANCE - FT & ENGINE POWER ~ SHP




FIG. 28 TIME HISTORY OF LANDING RUN NO. 13 ~ FLT. NO. 5B

206-194-134



SHIP NO. 41155<sup>1</sup> FLT. NO. 5B  
 CTR. NO. 928 ACT. GROSS WT. 2901 LB.  
 GROUND LEVEL PRESS. ALT. 650 FT  
 GROUND LEVEL AMBIENT TEMP. 90 °C  
 $\sigma^2 = .960$  ;  $\sqrt{\sigma^2} = .980$  ; DEN. ALT. 1380 FT  
 AVG. WIND SPEED (ALONG PATH) 16.0 FPS

NOTE: EVENT LIGHT NOT VISIBLE.

T.D. LOCATION FROM OBS. DATA  
 AND RUNWAY GRADIENT CORRELATION.

FOR TAKE-OFF DISTANCE  
 OBS. TO. DIST. FT. TIME TO 50 FT. HT. SEC.  
 NOMINAL ENGINE POWER  
 FOR LANDING DISTANCE  
 TIME, 50 FEET TO GROUND CONTACT 12.12 SEC.  
 ENTRY GROUND SPEED @ 50 FT. 83.0 FT/SEC.  
 GROUND CONTACT GROUND SPEED 31.3 FT/SEC.  
 RATE OF DESCENT AT 50 FT. 21.3 FT/SEC.  
 OBSERVED AIR LANDING DIST. 622 FT.  
 OBSERVED GROUND LANDING DIST. 143 FT.




FIG. 29 TIME HISTORY OF LANDING RUN NO. 14 ~ FLT. NO. 5B

OH-58A

36

206-194-134




FIG. 30 TIME HISTORY OF LANDING RUN NO. 15 ~ FLT. NO. 5B






FIG 31 TIME HISTORY OF AUTOROTATION LANDING

010000  
010000

OH-58A 39  
206-194-134

SHIP NO. 41155 DATE: 11-24-71  
GROSS WEIGHT 2845 LBS  
PRESSURE ALTITUDE 200 FT  
AIRSPEED ALTITUDE 200 FT  
DENSITY ALTITUDE 200 FT  
DENSITY ALTITUDE 200 FT

ENTRY HEIGHT (AT T.C.) 96.0 FT.  
ENTRY SPEED (AT T.C.)  
 $V_{GS} = 93.7 \text{ FPS} = 13.7 \text{ KTS. } V_{GS}$   
 $V_{MC} = 5.6 \text{ KTS.}$   
 $V_{TH} (V_{GS} + V_{MC}) = 49.8 \text{ KTS. } V_{CHL}$   
GROUND CONTACT = 22.0 FPS = 13.0 KTS.  $V_{GS}$   
ARMY PILOT, JOE WATTS




FIG. 32. TIME HISTORY OF HORIZONTAL DISTANCE, HEIGHT ABOVE GROUND AND MAIN ROTOR RPM ~ HEIGHT - VELOCITY RUN NO. 6

BY

CHECKED

HILL HELICOPTER COMPANY

MODEL OH-58A PAGE 40

SERIAL 206-194-134

MAIN ROTOR RPM

360  
340  
320  
300  
280  
260  
240

ENTRY HEIGHT (AT TC) 88.0 FT

ENTRY SPEED (AT TC)

 $\frac{45}{26} = 65.0 \text{ FPS} = 40.3 \text{ MTS. VGS.}$  $V_{W.C.} = 4.2 \text{ MTS.}$  $V_{T.C.} (V_{G.S.} + V_{W.C.}) = 44.9 \text{ MTS. VGS.}$ 

GROUND CONTACT = 16.5 FPS = 9.8 MTS. VGS.

ARMY PILOT, JOE WATTS

COLLECTIVE TRAVEL = 66.6% (% OF STD. TRAVEL)

SHIP NO. 41151 DATE 11-24-71

GROSS WEIGHT 29559 LBS.

PRESSURE ALTITUDE 200 FT

AMBIENT TEMPERATURE 70.0°C

DENSITY RATIO 0.9204  $\rho_{SL} = 1.010$ 

DENSITY ALTITUDE - 700 FT




FIG. 33. Time History Of Horizontal Distance, Height Above Ground  
And Main Rotor RPM - Helicopter - Velocity Run No. 7

37

CHECKED

L. S. L. HELICOPTER COMPANY  
POST OFFICE BOX 402  
ST. LOUIS, MO. 63101

104-58A

41

111

206-194-134

MAIN ROTOR ~ RPM

360  
340  
320  
300  
280  
260  
240

VERTICAL HEIGHT ~ FEET

100  
80  
60  
40  
20  
0

18

16

14

12

10

8

6

4

2

0

TIME ~ SECONDS

ENTRY HEIGHT (AT T.C.) 85.5 FT.

ENTRY SPEED (AT T.C.)

 $V_s = 62.0 \text{ FPS} = 50.7 \text{ MTS. V.S.}$  $V_{W.C.} = 4.2 \text{ MTS.}$  $V_{T.C.} (V_{O.S.} + V_{W.C.}) = 41.3 \text{ MTS. V.S.}$ 

GROUND CONTACT = 21.3 FPS = 12.6 MTS. V.S.

ARMY PILOT, JOE WATTS

SHIP NO. 4111 DATE: 11-24-71

GROSS WEIGHT 2954 LBS.

PRESSURE ALTITUDE 200 FT.

AMBIENT TEMPERATURE 70C

DENSITY RATIO 0.91021  $\rho/\rho_0 = 1.010$ 

DENSITY ALTITUDE -100 FT.

COLLECTIVE TRAVEL = 67.0% (% OF STD. TRAVEL)

STOP

ROTOR

RPM

THROTTLE

CHOP

HORIZONTAL

GROUND

CONTACT

VERTICAL

HORIZONTAL DISTANCE ~ FT.

1000

800

600

400

200

0

FIG. 34. TIME HISTORY OF HORIZONTAL DISTANCE, HEIGHT ABOVE GROUND

AND MAIN ROTOR RPM ~ HEIGHT - VELOCITY RUN NO. 8



REF. NO. 41155  
 FLT. NO. ARMY  
 DT. 11-14-71  
 GRID NO. 9

NOTE: CURVE OBTAINED FROM TABLE  
 OBSERVED READINGS OF REF. L  
 TRUCK AT VARIOUS RUNWAY  
 LOCATIONS USING THE FPA  
 GRID CAMERA

AS READ FROM THE 100 GRID CAMERA




Fig 35 Runway 16-34 Gradient @ Arlington Municipal Airport, Texas

PRG. NO. F0132 MODEL OH-58A S/N 41080 DATE 9-30-71 1ST REC 0539  
 PROGRAM T/B FAILURE INVESTIGATION CHANGE LETTER B 1ST FLT 2

SET UP ITEM DESCRIPTION DELTA CAL REF VALUE UNITS TRACK 1

TABLE I Sheet 1 of 4

01-01-0483	F101	M/R RED PITCH LINK	1284.21	0.00	LBS	
01-02-0539	B103	M/R RED YOKE CHD BEND	107589.33	0.00	IN-LB	
01-03-0539	B102	GROUND CONTACT INDICATOR	0.00000	0.00000		
01-04-0483	D104	M/R FLAPPING	184.48963	100.00001	%	
01-05-0483	D021	F/A CYCLIC STK POSITION	99.90400	50.00000	%	
01-06-0483	D022	LAT CYCLIC STK POSITION	75.79881	50.00000	%	
01-07-0483	D023	COLL STK POSITION	105.86958	0.00000	%	
01-08-0483	D051	F/A PYLON MOUNT MOTION	91.88653	60.55000	%	
01-09-0483	D052	LAT PYLON MOUNT MOTION	116.88656	28.30000	%	
01-10-0483	S251	R/H LONGERON STRESS STA 176	24354.79	0.00	PSI	
01-11-0483	S252	T/B LOWER SKIN STRESS STA 219	24350.70	0.00	PSI	
01-12-0483	S253	L/H LONGERON STRESS STA 176	48810.96	0.00	PSI	
01-13-0483	R018	M/R AZIMUTH	0.00000	0.00000		

TABLE I Sheet 2 of 4  
Instrumentation Set-Up Sheet, S/N 5610

Purpose: Tailboom Evaluation			Flight: 1	Date: 9-29-71	Ref.
Chan.			100 K		
No.	Measured and Location	Sta.	Lab No.	C.E.	Units Value
1	Engine Torque Pressure		8761	27.2	psi 0
2	Hydraulic Pressure		8785	252.7	psi 0
3	Center of Gravity Vertical Acceleration		14649	1.09	g 1.0
4	C.L. Hub F/A Acceleration		2041	1.365	g 0
5	C.L. Hub Lateral Acceleration		2040	1.29	g 0
6	R/H Cyclic Boost Tube		5903C	731	lb 0
7	L/H Cyclic Boost Tube		5904C	751	lb 0
8	Collective Boost Tube		7557A	918	lb 0
9	M/R Feathering		7894	14.65	deg -
13	M/R rpm (Linear)			C.C. 54.0	rpm/in. -
17	Skid Gear Ground Contact		-	-	-
18	M/R Azimuth		-	-	-

BY \_\_\_\_\_

CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY

POST OFFICE BOX 482

FORT WORTH 1, TEXAS

MODEL OH-58A PAGE 44

RPT 206-194-134

PROG. NO. F0132    MODEL OH-58A    S/N 41155    DATE 10-9-71    1ST REC 0617  
 PROGRAM TAILBOOM INVESTIGATION    CHANGE LETTER C    1ST FLT 1

SET UP    ITEM    DESCRIPTION    DELTA CAL    REF VALUE    UNITS    TRACK 1

TABLE I Sheet 3 of 4

01-01-0617	B102	GROUND CONTACT INDICATOR	0.00000	0.00000		
01-02-0617	D104	M/R FLAPPING	145.79598	100.00001	%	
01-03-0617	D023	COLLECTIVE STK POSITION	105.15599	0.00000	%	
01-04-0617	D021	F/A CYCLIC STK POSITION	96.85609	50.00000	%	
01-05-0617	D022	LAT CYCLIC STK POSITION	138.17599	50.00000	%	
01-06-0617	D051	F/A PYLON POSITION	153.65130	39.41000	%	
01-07-0617	D052	LAT PYLON POSITION	204.35375	71.70001	%	
01-08-0617	B106	M/R MAST PARA BEND STA 18	42786.73	0.00	IN-LB	
01-09-0617	B103	M/R RED YOKE CHORD BEND	110712.18	0.00	IN-LB	
01-10-0617	B105	M/R RED BLADE BEAM BEND	20842.76	-3039.00	IN-LB	
01-11-0617	S253	L/H LONGERON STRESS	49639.97	0.00	PSI	
01-12-0617	S252	T/B LOWER SKIN STRESS STA 219	49783.66	0.00	PSI	
01-13-0483	R018	M/R AZIMUTH	0.00000	0.00000		



TABLE I Sheet 4 of 4  
Instrumentation Set-Up Sheet, S/N 5632

Purpose: Tailboom Failure Investigation

Date: 10-9-71

Flight: 100 K

Chan. No.	Measured and Location	Sta.	Lab No.	C.E.	Units	Ref. Value
1	M/R Blade Angle		7894	14.65	deg	-
2	M/R Pitch Link, Red		5875B	876	lb	0
3	M/R Mast Parallel Bending	35.87	5865D-06	10,830	in.lb	0
4	M/R Mast Perpendicular Bending	18	5865D-03	7082	in.lb	0
5	Center of Gravity Vertical Accel.		14699	1.09	g	1.0
6	90° Gear Box Vertical Acceleration		16950	4.748	g	1.0
7	90° Gear Box Lateral Acceleration		5566	4.783	g	0
8	Tailboom Skin Vertical Stress	228	7916A	16,768	psi	-
9	Tailboom Skin Lateral Stress		7916A	16,768	psi	-
10	R/H Longeron Stress		7915	16,768	psi	-
11	Ground Contact Indicator		-	-	-	-
17	Throttle Chop Event		-	-	-	-
18	M/R Azimuth		-	-	-	-

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
POST OFFICE BOX 482 • FORT WORTH 1, TEXAS

MODEL OH-58A PAGE 46  
RPT 206-194-134



Sheet 2 of 2

## TABLE II

## LOG OF FLIGHTS

G. R. No.	Flt No.	Date	Time (hr)	G. W. (lb)	C. G. Sta.	Configuration/Purpose
<u>OH-58A S/N 41155 - (cont)</u>						
	3A	10-20	0.5	2986	109.6	Record and evaluate a series of autorotation landings with collective up stop restricted to 85% or 14.7° main rotor blade angle.
	4	10-21	0.4	2712	108.6	Continue autorotation landings with reduced available collective.
	5A	10-25	0.5	2984	109.6	Autorotation landing with collective stop reduced to 80%.
	5B	10-25	0.9	2984	109.6	"
	5C	10-25	0.1	2984	109.6	"
	6	11-19	0.3	2700	108.5	Shakedown for USAASTA Evaluation. Standard collective bellcrank.
	7A	11-23	0.1	2700	108.6	Shakedown.
	7B	11-23	0.4	2700	108.6	USAASTA Evaluation.
	7C	11-23	0.4	2700	108.6	USAASTA Evaluation with 80% collective available.
	8A	11-24	0.1	3000	109.6	USAASTA height-velocity evaluation.
	8B	11-24	0.8	3000	109.6	"

BY \_\_\_\_\_  
CHECKED \_\_\_\_\_BELL HELICOPTER COMPANY  
POST OFFICE BOX 482 • FORT WORTH, TEXASMODEL OH-58A PAGE 48  
RPT 206-194-134

BY _____	BELL HELICOPTER COMPANY POST OFFICE BOX 482 • FORT WORTH 1, TEXAS	MODEL <u>OH-58A</u> PAGE <u>49</u>
CHECKED _____		RPT <u>206-194-134</u>

TABLE III  
OSCILLOGRAPH PARAMETERS  
S/N: 41155 MODEL: OH-58A FLIGHT: 5B DATE: 22 OCT. 71

RUN NO.	CTR NO.	GROUND CONTACT GROUND SPEED ~ KTS	COLLECTIVE POSITION @ CONTACT ~ %	F/A CYCLIC POSITION @ CONTACT ~ %	N <sub>R</sub> @ CONTACT ~ RPM	N <sub>R</sub> @ LOWERED COLLECTIVE ~ RPM	% OF FLAPPING @ CONTACT ~ %	% OF FLAPPING @ LOWERED COLLECTIVE ~ %
10	924	18.53	57.7	37.9	258	144	± 32.0	± 16.2
11	925	28.10	57.7	41.3	264	138	± 32.0	± 17.6
12	926	25.46	80.4	52.8	228	186	± 64.8	± 13.5
13	927	29.30	70.1	54.5	228	198	± 62.2	± 18.9
14	928	18.53	80.4	44.6	225	132	± 62.2	± 21.6
15	929	32.26	78.3	53.7	240	132	± 62.1	± 32.4

OTHER INFORMATION:

GROSS WEIGHT 2936 TO 2891 LBS. DURING RUNS 10-15

GROUND LEVEL H<sub>D</sub> 1380 FT.

GROUND LEVEL AMBIENT TEMP. 20°C



BY \_\_\_\_\_  
CHECKED \_\_\_\_\_

BELL HELICOPTER COMPANY  
POST OFFICE BOX 402 FORT WORTH, TEXAS

MODEL OH-58A PAGE 50

RPT 206-194-134

TABLE IV (SHEET 1 OF 3)  
FAA GRID CAMERA DATA

☐ TAKE OFF DISTANCE ☐ LANDING DISTANCE ☒ HEIGHT VELOCITY  
BELL S/N 41155 LOCATION ARLINGTON, TEXAS

FLT. NO.	RUN NO.	OBS. TIME  SEC.	OBS. DISTANCE		VERTICAL READING { GRADIENT CORR. (NOTE: 1) FT.	CORR. TIME (1) @ NOTE: 2  SEC.	CORR. DISTANCE		REMARKS
			VERT.  FT.	HORIZ.  FT.			VERT.  (2) + (4) FT.	HORIZ.  (3) @ (NOTE: 2) FT.	
ARMY	6	10.04	121	6583	21.5	0	99.5	0	
A	A	10.84	120	6526		0.80	98.5	57	
		11.64	119	6468		1.60	97.5	115	
		12.44	118	6408		2.40	96.5	175	
		13.44	117.5	6334		3.40	96	249	
		14.24	117.5	6276		4.20	96	307	
		14.64	117.5	6247		4.60	96	336	LIGHT ON
		15.44	117	6188		5.40	95.5	395	
		16.24	116.5	6130		6.20	95	453	
		17.24	112.5	6057		7.20	91	526	
		18.24	98	5984		8.20	76.5	599	
		19.24	72	5911		9.20	50.5	672	
		20.24	48	5842		10.20	26.5	741	
		21.24	33	5781		11.20	11.5	802	
		22.24	30	5738		12.20	8.5	845	
		23.24	27.5	5705		13.20	6.0	878	
		24.24	22	5679		14.20	0.5	904	
		25.25	22	5651		15.21	0.5	927	
		25.65	21.5	5647	21.5	15.61	0	936	LIGHT OUT
		26.65	21.5	5628		16.61	0	955	
	V	27.86	21.5	5614		17.82	0	969	
	6	28.47	21.5	5613		18.43	0	974	STOP
	7	15.88	106	6401	21.5	0	84.5	0	
	A	16.68	107	6348		0.80	85.5	53	
		17.68	108	6283		1.80	86.5	118	
		18.69	109	6218		2.81	87.5	183	
		19.49	109.5	6164		3.61	88	237	
		20.10	109.5	6124		4.22	88	277	
		20.49	109.5	6087		4.61	88	304	LIGHT ON
		21.10	109	6055		5.22	87.5	346	
		22.10	105	5987		6.22	83.5	414	
		23.10	93.5	5919		7.22	72	482	
		24.10	69	5849		8.22	47.5	552	
	V	25.11	44	5780		9.23	22.5	621	
ARMY	7	26.11	32	5702	21.5	10.23	10.5	679	

- NOTE: (1) CORRECTION OF READING (MAST) TO GROUND (SKID-GEAR): - 9.5 FT. PLUS RUNWAY GRADIENT CORRECTION (FIG. \_\_\_\_\_) USING THE TOUCHDOWN POINT FOR HEIGHT VELOCITY AND LANDING AND THE HOVER POINT FOR TAKE-OFF.
- (2) CORRECTED TIME ZERO AND HORIZONTAL DISTANCE ZERO TO BE START OF TAKE-OFF RUN, APPROX. 1 SEC. PRIOR TO THROTTLE CHOP FOR HT. VELOCITY, AND ANY TIME PRIOR TO 50 FT. HEIGHT FOR LANDING.

J.G. 11-29-71

BY _____	<b>BELL HELICOPTER COMPANY</b> <small>POST OFFICE BOX 487 • FORT WORTH 1, TEXAS</small>	MODEL <u>OH-58A</u> PAGE <u>51</u> RPT. <u>206-194-134</u>							
CHECKED _____									
<b>TABLE IV</b> (SHEET <u>2</u> OF <u>3</u> ) <b>FAA GRID CAMERA DATA</b>									
<input type="checkbox"/> TAKE OFF DISTANCE <input type="checkbox"/> LANDING DISTANCE <input checked="" type="checkbox"/> HEIGHT VELOCITY BELL S/N <u>41155</u> LOCATION <u>ARLINGTON, TEXAS</u>									
FLT. NO.	RUN NO.	OBS. TIME SEC.	OBS. DISTANCE		VERTICAL READING & GRADIENT CORR. (NOTE: 1) FT.	CORR. TIME ① ② NOTE: 2 SEC.	CORR. DISTANCE		REMARKS
			VERT. FT.	HORIZ. FT.			VERT. ② + ④ FT.	HORIZ. ③ ⑤ (NOTE: 2) FT.	
ARMY 6	7	27.12	29.5	5681	21.5	11.24	8	700	
	A	28.12	25.5	5652	↓	12.24	4	749	
		29.12	22.0	5632	↓	13.24	0.5	769	
		29.92	21.5	5619	21.5	14.04	0	782	LIGHT OUT
	Y	30.92	21.5	5608		15.04		793	
	7	31.92	21	5604		16.04		797	STOP
	8	10.60	115	6246	22	0	93	0	
	A	11.60	114	6178	↓	1.00	92	68	
		12.60	113	6112		2.00	91	134	
		13.61	111	6049		3.01	89	197	
		14.61	109.5	5987		4.01	87.5	259	
		15.42	107.5	5937		4.82	85.5	309	LIGHT ON
		16.43	101.5	5877		5.83	79.5	369	
		17.44	93	5815		6.84	71	431	
		18.45	72	5751		7.85	50	495	
	19.45	48	5689		8.85	26	557		
	20.46	33	5633		9.86	11	613		
	21.47	29.5	5592		10.87	7.5	654		
	22.48	25	5560		11.88	3	686		
	23.49	22.5	5538	Y	12.89	0.5	708		
	23.69	22	5533	22	13.09	0	713	LIGHT OUT	
	24.71	22	5516		14.11		730		
Y	Y	25.72	22	5505		15.12		741	
ARMY	8	26.37	22	5503		15.73		743	STOP

NOTE: (1) CORRECTION OF READING (MAST) TO GROUND (SKID-GEAR): - 9.5 FT. PLUS RUNWAY GRADIENT CORRECTION (FIG. \_\_\_\_\_) USING THE TOUCHDOWN POINT FOR HEIGHT VELOCITY AND LANDING AND THE HOVER POINT FOR TAKE-OFF.

(2) CORRECTED TIME ZERO AND HORIZONTAL DISTANCE ZERO TO BE START OF TAKE-OFF RUN, APPROX. 1 SEC. PRIOR TO THROTTLE CHOP FOR HT. VELOCITY, AND ANY TIME PRIOR TO 50 FT. HEIGHT FOR LANDING.

BY _____	BELL HELICOPTER COMPANY POST OFFICE BOX 487 • FORT WORTH, TEXAS	MODEL <u>OH-58A</u> PAGE <u>52</u>
CHECKED _____		RPT <u>206-194-134</u>

**TABLE IV** (SHEET 3 OF 3)  
**FAA GRID CAMERA DATA** RUNWAY GRADIENT

☐ TAKE OFF DISTANCE    ☐ LANDING DISTANCE    ☒ HEIGHT VELOCITY  
 BELL S/N 41155    LOCATION ABELINGTON, TEXAS

FLT. NO.	RUN NO.	OBS. TIME	OBS. DISTANCE		VERTICAL READING { GRADIENT CORR. (NOTE: 1) FT.	CORR. TIME (NOTE: 2) SEC.	CORR. DISTANCE		REMARKS
			VERT. FT.	HORIZ. FT.			VERT. (2)+(4) FT.	HORIZ. (3)+(5) (NOTE: 2) FT.	
ARMY	9		30	3850	6		24	3850	
			29.5	4000			23.5	4000	
			28	4150			22	4150	
			26	4300			20	4300	4
			24	4450			18	4450	3
			23	4600			17	4600	1
			22.5	4750			16.5	4750	6
			21.5	4900			15.5	4900	1
			21	5000			15	5000	
			20.5	5100			14.5	5100	
			20	5200			14	5200	7
			19.5	5300			13.5	5300	
			19	5400			13	5400	1
			18.5	5500			12.5	5500	1
			18.5	5600			12.5	5600	
			18	5700			12	5700	
			17.5	5800			11.5	5800	
			17	5900			11	5900	6
			16.5	6000			10.5	6000	
			16.5	6100			10.5	6100	
			16	6200			10	6200	4
			16	6300			10	6300	
			15.5	6400			9.5	6400	
			15.5	6500			8.5	6500	
			14.5	6600			8.5	6600	
			14	6700			8	6700	
			13.5	6800			7.5	6800	
ARMY	9		12.5	6900	6		7.5	6900	

NOTE: (1) CORRECTION OF READING (MAST) TO GROUND (SKID-GEAR): \_\_\_\_\_ FT.  
 PLUS RUNWAY GRADIENT CORRECTION (FIG. \_\_\_\_\_) USING THE  
 TOUCHDOWN POINT FOR HEIGHT VELOCITY AND LANDING AND THE  
 HOVER POINT FOR TAKE-OFF.  
 (2) CORRECTED TIME ZERO AND HORIZONTAL DISTANCE ZERO TO BE START OF  
 TAKE OFF RUN, APPROX. 1 SEC. PRIOR TO THROTTLE CHOP FOR HT. VELOCITY,  
 AND ANY TIME PRIOR TO 50 FT. HEIGHT FOR LANDING.



DISTRIBUTION LIST

- 1 - Kelley/Lynn/Library
- 1 - Flight Test
- 1 - 206 Project
- 1 - Galerstein
- 3 - USAAVSCOM
- 5 - USAMC
- 1 - BPA
- ~~22~~  
12 - DDC



